

9113 Sandoval



**BUILDING AND STANDARDS BOARD AGENDA ITEM #7 FOR
WEDNESDAY, MARCH 26, 2014**

**ENVIRONMENTAL SERVICES DEPARTMENT
CODE COMPLIANCE DIVISION**

MEMORANDUM
March 11, 2014

TO: The Honorable Chairman and Board Members

THROUGH: Elda Rodriguez-Hefner, Division Manager, Code Compliance Department

FROM: Ron Roth, C.B.O., Deputy Building Official

SUBJECT: 9113 Sandoval, El Paso, Texas, 79907

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated on or about October 26th, 2011 and most recently, October 9th, 2012. The structures were found occupied without any utilities, trash service or minimum required facilities. There was urine being discharged through the front window and there was a strong odor of human feces throughout the dwelling. The structures were found to be in an advanced state of disrepair, the rear wall supported by an Adobe stem wall is protruding outward and nearing collapse. There are numerous structural cracks throughout the CMU walls.
- 2) A certified condemnation letter was mailed to Roberto Loera, 305 Alton Griffin St., Ysleta Del Sur Pueblo, TX 79907
- 3) Certified notices of the public hearing scheduled for March 26, 2014, were mailed to the owners and all interested parties on MARCH 06, 2014.
- 4) As of March 12, 2014, **\$9,831.39** is owed in taxes.

The owner has been notified of the property violations at this property, to date there has been no response or corrective action taken, and therefore the Department recommends that it be found:

- 1) That the structures be condemned as substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare; and
- 2) That the structures are not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
- 3) That the structure's certificate of occupancy be revoked; and
- 4) That the structures cannot be rehabilitated; and
- 5) That all the structures be **demolished** within thirty (30) days; and
- 6) That the premises be cleaned and maintained clean of all weeds, trash, and debris within 30 days; and
- 7) That upon failure by the owner or any other interested party to comply with the order of the Building and Standards Commission the City may take whatever action is necessary to bring the property into compliance, and place a lien on the property for the work which will be done by the City.

Code Compliance Division
October 16, 2012

NOTICE OF VIOLATION

Roberto Loera
305 Alton Griffin St.
Ysleta Del Sur Pueblo, TX 79907

Re: 9113 Sandoval Ct.
Blk: 1 Loera Subdivision
Lot: 1
Zoned: R-4H
Case Number: ENHS12-00795
Mail Receipt: 7108 2133 3932 6909 1623

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

18.50.108.1 General.

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Title 2.38 of the Municipal Code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

18.50.108.1.1 Unsafe Structures.

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible.

18.50.108.1.2 Unsafe Equipment

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.108.1.3 Structure Unfit for Human Occupancy.

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public

The structure located at **9113 Sandoval Ct, El Paso, 79907**, is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. All *exterior property*, *accessory structures* and *premises* shall be maintained in a clean, safe and sanitary condition, All accessory structures, including *detached* garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- d. All *exterior property* and *premises*, and the interior of every structure, shall be free from any accumulation of *rubbish* or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- e. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Environmental Services Department, Code Compliance Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Prosecutor's Office for court proceedings. The court will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Title 2.38 of the El Paso Municipal Code.
- b. By authority of Chapter 18.02.103.10.3.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the Environmental Services Department, Code Compliance Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Code Compliance Division office, 7969 San Paulo Dr., El Paso, Texas, 79907, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at 599-6290.

Cesar A. Grado
Building Inspector

NOTICE OF PUBLIC HEARING

To all interested parties:

The owners, mortgagee, lien holders and any others with a legal interest in the property described below are hereby ordered to appear before the Building and Standards Commission, herein after referred to as the "Commission", at the following time and place:

LOCATION: : City Hall, City Council Chambers, 300 N. Campbell Street, 1st Floor, El Paso, Texas 79901

DATE: March 26, 2014

TIME: 5:30 p.m.

PROPERTY: 9113 Sandoval, EL PASO, TEXAS also described as Lot 1, Block 1, Loera Subdivision to the City of El Paso, El Paso County, Texas.

The Property has been determined to be substandard based upon violations of the minimum standards of the 2009 Building Codes, adopted and incorporated in the El Paso City Code, Chapter 18, more specifically addressed below.

According to the real property records of El Paso County, and other relevant public records, Roberto Loera and the Estate of Guadalupe H. Loera, 305 Alton Griffin St., Ysleta Del Sur Pueblo, TX, are the owners, herein after referred to as the "Owner" of the Property. If you no longer own or have an interest in the Property, you must execute an affidavit stating that you no longer own or have an interest in the Property and stating the name and last known address of the person who acquired the property from you, if applicable. The affidavit must be delivered in person or by certified mail, return receipt requested, to Code Compliance Division of Environmental Services, 7969 San Paulo Drive, El Paso, Texas 79907, no later than the 20th day after the date you receive this notice. If you do not execute and deliver the affidavit, it will be presumed that you own or have an interest in the Property, even if you do not.

On or about October 16th, 2012, an inspection of the Property was conducted by the Environmental Services Division and the following violations were identified:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2,

304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]

- c. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- d. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]

The Owner is entitled to show cause that the Property is safe, does not constitute a dangerous structure and should not be declared a nuisance and ordered abated by presenting relevant evidence and testimony. If the Owner advocates for repair, then they bear the burden of proof to demonstrate the scope of any work that may be required to bring the property into compliance with Chapter 18.50 and the time it will take to reasonably perform the work. The allowable time periods for repair are governed by Texas Local Government Code, Sections 214.001(h), (i), (j) and (k). Any document relied upon to demonstrate that the Property is safe or that it can be repaired must be presented to the Commission at the hearing, including building plans, specifications, drawings, or reports from professionals and any other relevant documentation.

If the Owner fails to comply with the order of the Commission the City may pursue one or more of the following actions:

Perform any and all work necessary to bring the property into compliance with the Commission's order;

Assess civil penalties, provided for in the Commission's order, in an amount not to exceed \$1,000 per day or \$10 per day if the Property has a homestead exemption, that will accrue interest of 10% per year until paid in full;

Appoint a receiver as permitted by state law; and

Any other remedies permitted by state law.

Commission orders may be appealed to the State District Court within 30 days of the Final order.

The Commission's authority and procedures in regard to a Dangerous Structure Hearing may be found in Chapter 2.38 of the El Paso City Code and in their duly adopted bylaws. A copy of the ordinance adopting the most current version of Chapter 2.38 is enclosed. The bylaws may be obtained at the Code Compliance Division of Environmental Services, 7969 San Paulo Drive, El Paso, Texas 79907 or by calling (915) 599-6290.

This notice will be recorded in the real property records of El Paso County and will be binding on subsequent grantees, lien holders or other transferees of an interest in the Property.

The City Clerk is ordered to provide notice of this hearing to the record owners and all other interested parties, required by law, who are listed following this notice, and file this notice in the real property records of El Paso County.

FAILURE OF THE OWNER AND/OR LIENHOLDER OR MORTGAGEE TO TAKE THE ORDERED ACTION MAY RESULT IN THE CITY TAKING THE ORDERED ACTION AND FILING A LIEN AGAINST THE PROPERTY.

The City of El Paso appreciates your cooperation and prompt attention to remedying the nuisances on the Property. Please do not hesitate to contact me should you have any additional questions, comments or concerns relative to this notice.

APPROVED AS TO FORM

APPROVED AS TO CONTENT

John R. Batoon or Wendi N. Vineyard
Assistant City Attorney

Ron Roth, C.B.O.
Deputy Building Official

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice regarding the property located at 9113 Sandoval, El Paso, Texas was PUBLISHED in the official City newspaper on the ____ day of _____, 2014.

Richarda Duffy Momsen

I certify that a true and correct copy of the foregoing Notice regarding the property at 9113 Sandoval, El Paso, TX, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Roberto Loera and the Estate of Guadalupe H. Loera
305 Alton Griffin St.
Ysleta Del Sur Pueblo, TX 79907-6811

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 9113 Sandoval, El Paso, TX, was HAND-DELIVERED to:

City of El Paso
C/O City Clerk
300 N. Campbell
El Paso, TX 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 9113 Sandoval, El Paso, TX, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Governor of the Ysleta Del Sur Pueblo Indian Tribe
AKA Tigua Indian Community
119 S. Old Pueblo Road
El Paso, Texas 79907

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 9113 Sandoval, El Paso, TX, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso Central Appraisal District
5801 Trowbridge Ave.
El Paso, Texas 79925

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 9113 Sandoval, El Paso, TX, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso County Clerk, Probate Dept.
500 E. San Antonio Avenue, Suite 105
El Paso, Texas 79901

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 9113 Sandoval, El Paso, TX, was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Delgado, Acosta, Spencer
Linebarger, Heard & Perez, LLP
Attn: Bonnie Cooper
221 N. Kansas Suite 1400
El Paso, TX 79901

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice was POSTED at 9113 Sandoval, El Paso, Texas.

Date: _____

Time: _____

Inspector: _____



UNSAFE STRUCTURES REPORT

BUILDING PERMITS AND INSPECTIONS

DATE OF EXAMINATIONS: 10-26-11 , 10-09-12

REP. DISTRICT: 6

ADDRESS: 9113 Sandoval

ZONED: R-4H

LEGAL DESCRIPTION: Lot 1, Block 1, Loera Subdivision to the City of El Paso, El Paso County, Texas.

OWNER: Roberto Loera

ADDRESS: 305 Alton Griffin St., Ysleta Del Sur Pueblo, TX

BUILDING USE: Single Family Dwelling

TYPE OF CONSTRUCTION: V

FOOTINGS: Concrete

CONDITION: Unable to determine condition of footing due to subterranean placement. A structural engineer should be hired to evaluate the actual condition.

FOUNDATION WALL: Adobe stem wall

CONDITION: Poor, cracked and crumbling, insufficient to carry wall load.

FLOOR STRUCTURE: Concrete slab on grade with VCT tile

CONDITION: Poor

EXTERIOR WALLS: Front 2/3rd of structure C.M.U. with brick veneer. Rear 1/3 wood frame with vertical siding.

HEIGHT: 12 +/-

THICKNESS: 12" +/-

CONDITION: Poor. Large structural cracks throughout brick veneer and underlying C.M.U.

INTERIOR WALLS & CEILINGS: Gypsum wallboard over wood framing.

CONDITION: Poor. Large sections of drywall missing in ceilings and walls, exposing underlying structural elements.

ROOF STRUCTURE: Pitched roof with mineral rolled roofing.

CONDITION: Poor. Lacking maintenance, allowing entrance of water.

DOORS, WINDOWS, ETC.: Does not meet means of egress.

CONDITION: N/A

MEANS OF EGRESS: Insufficient.

CONDITION: Does not meet Code requirements

PLUMBING: Inadequate and poorly maintained.

CONDITION: A licensed plumbing contractor should be hired to evaluate the plumbing system.

ELECTRICAL: Exposed wiring throughout structure. Does not meet Code Requirements.

CONDITION: A licensed electrical contractor should be hired to evaluate the electrical system.

MECHANICAL: Inadequate or nonexistent.

CONDITION: A licensed mechanical contractor should be hired to evaluate the mechanical system.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED: 1

WARNING POSTED: No

BARRICADED: No

POLICE AID REQD.: No

REMARKS: This single family residence was constructed in 1943. The structures were found occupied with no utilities, trash service, or minimum required facilities. The structures are in an advanced state of disrepair. The rear wall supported on Adobe stem wall is leaning outward, and there are numerous structural cracks in C.M.U. walls. The department recommends that the structures be demolished within thirty (30) days as it poses a health and fire hazard, and also be cleaned of all weeds, trash and debris within thirty (30) days.

CESAR A. GRADO

Building Inspector

TAX REPORT

Appraisal & Collection Technologies - EL PASO

Action Edit Query Record Field Help Entitlements Accounts Statements Window

ORACLE

Account Status

Prev. Acc... Next Acc... Prev. Owner Next Owner Acct History Acct Summary **Notes** Documents Go To:

EVAR 03/12/2014 09:02:
ACT8006 v1.242 ACTEP

STATUS DETAIL Expand Fees Summary

Account Information

Account No. L430-999-0010-0100 Roll Code REAL PROPERTY

Certified Owner LOERA ROBERTO

Parcel Address 9113 SANDOVAL CT

Amount Due as of 03/12/2014 CAD No. 11863

Tax Units

Tax Unit Description

List of Tax Units

1 5 6 7 8 9009 9089

AG INCLUDED Remove Fees Countywide

Tax Unit, Yr, Rec. Type

Tax Unit Year Rec. Type

Multi Select

Amount Due/Paid Information

Year	Gross Value	H	O	V	D	Base Levy	Paid Levy	Write-Off	Remaining Levy	Fees	Refund	Amount Due
2013	\$41,417					\$1,163.93	\$0.00	\$0.00	\$1,163.93	\$295.06	\$0.00	\$1,458.99
2012	\$41,417					\$1,875.80	\$0.00	\$0.00	\$1,875.80	\$568.32	\$0.00	\$2,444.12
2011	\$29,995					\$797.09	\$0.00	\$0.00	\$797.09	\$518.91	\$0.00	\$1,316.00
2010	\$29,995					\$790.83	\$0.00	\$0.00	\$790.83	\$628.58	\$0.00	\$1,419.41
2009	\$30,538					\$789.83	\$0.00	\$0.00	\$789.83	\$741.17	\$0.00	\$1,531.00
2008	\$30,783					\$798.44	\$0.00	\$0.00	\$798.44	\$863.83	\$0.00	\$1,662.27
						Excodes						
						Excodes						
						Excodes						
Totals						\$6,215.92	\$0.00	\$0.00	\$6,215.92	\$3,615.87	\$0.00	\$9,831.79

Last Payment Date Last Payer

Alert

Show hidden icons

8:02 AM 3/12/2014